



Shop:
Tel:
Address:

Report ID: MAXIA20230517
Creation Date: 2023-05-17



Cummins Vehicle Diagnostic Report

License Plate: 17PB029

Manufacturer: Cummins

Year:

Model:

Sub Model:

Engine:

Path: Cummins>Auto scan>ISX12 CM2350 X102/X103/X108/ISX15 CM2350 X101/X104/X109>Trouble codes

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
DTC:195	Coolant level sensor 1 circuit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:4289	Accelerator pedal/lever position sensor 1 circuit frequency - abnormal frequency or pulse width or period	Active Lamp: Red Count: 1
DTC:4149	Accelerator pedal/lever position sensor 2 circuit frequency - abnormal frequency or pulse width or period	Active Lamp: Amber Count: 1
DTC:6339	Fuel level 1 - abnormal update rate	Active Lamp: Amber Count: 1
DTC:1845	Water In Fuel (WIF) indicator sensor circuit voltage above normal or short to high voltage	Active Lamp: Maintenance Count: 1
DTC:249	Ambient Air Temperature (AAT) sensor 1 circuit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:3868	Aftertreatment Diesel Exhaust Fluid (DEF) quality update rate abnormal	Active Lamp: Amber Count: 1
DTC:6688	Aftertreatment 1 particulate sensor - abnormal update rate	Active Lamp: Amber Count: 1