

2010 INTERNATIONAL Vehicle Diagnostic Report

Vehicle Information

2010/INTERNATIONAL/4300/
VIN: 1HTMMAAL8AH178474

Odometer Reading: --
License Plate: 10IH215

Customer Information

Name: --

Tel: --

Device information

Scanner: MaxiSys MS909CV
Version: V1.00-1.20

Serial Number: V19GM4V01249
Repair Order Number:
V19GM4V0124920241022152116788

DTC (7)

DTC	Description	Status
SPN:593 FMI:14 Code:2324	Engine stopped by IST	Inactive Count:0
SPN:597 FMI:2 Code:1222	Brake switch circuit fault	Inactive Count:0
SPN:8321 FMI:7 Code:2175	Variable Geometry Turbo (VGT) performance fault	Inactive Count:0
SPN:8330 FMI:7 Code:2545	ECM unable to receive body controller CAN messages	Inactive Count:0
SPN:94 FMI:1 Code:2372	Fuel pressure below normal	Inactive Count:0
SPN:8029 FMI:2 Code:1215	Remote throttle signal CAN error present	Inactive Count:0
SPN:102 FMI:4 Code:1122	Manifold Absolute Pressure (MAP) signal out of range low	Inactive Count:0

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.