

# 2007 WESTERNSTAR Vehicle Diagnostic Report

## Vehicle Information

2007/WESTERNSTAR/4900 Set Forward Axle/  
VIN: 5KJJAECKX7PX42048

Odometer Reading: 000miles  
License Plate: 07WS021

## Customer Information

Name: --

Tel: --

## Device information

Scanner: MaxiSys MS909CV  
Version: V1.34

Serial Number: V19GM4V01376  
Repair Order Number:  
V19GM4V0137620251201130841547

## DTC ( 8 )

| DTC                              | Description   | Status                |
|----------------------------------|---|-----------------------|
| Master ECM:<br>PID 100<br>FMI 1  | Oil pressure low  | Inactive<br>Count 4   |
| Master ECM:<br>PID 110<br>FMI 0  | Coolant temperature high  | Inactive<br>Count 58  |
| Master ECM:<br>PID 111<br>FMI 1  | Coolant level low   | Inactive<br>Count 59  |
| Master ECM:<br>SID 147<br>FMI 2  | Variable Nozzle Turbocharger (VNT) vanes not responding - boost power | Inactive<br>Count 9   |
| Master ECM:<br>PID 110<br>FMI 14 | Engine power derate due to coolant temperature                        | Inactive<br>Count 144 |
| Master ECM:<br>PID 105<br>FMI 14 | Engine power derate due to inlet manifold temperature                 | Inactive<br>Count 13  |
| Master ECM:<br>PID 172<br>FMI 0  | Air inlet temperature high  | Inactive<br>Count 4   |
| Master ECM:<br>SID 21<br>FMI 1   | Too few SRS (missing SRS)   | Inactive<br>Count 1   |

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.