

Shop: --Tel: --Email: --

Address: --

Report ID: MAXIA20250604114050 Test Time: 2025-06-04 11:40:50

Technician: --

HD OBD VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/HD OBD/SAE J1939/ Odometer Reading: --VIN: -- License Plate: --

Customer Information

Name: -- Tel: --

Device information

Scanner: MaxiSys CV Serial Number: V09G60107202 Version: V6.80 Repair Order Number: --

System Scanned(2)

System	Status/DTC
SAE J1939	② 0
SAE J1708/J1587	② 0

🔼 DTC (19)

Cab controller - primary (4 DTCs)

DTC	Description	Status
SPN 3698,FMI 9	Exhaust system high temperature lamp command Abnormal update rate	Cab controller - primary Active Count : 126
SPN 3697,FMI 9	Diesel particulate filter lamp command Abnormal update rate	Cab controller - primary Active Count : 126
SPN 886,FMI 9	Headway controller forward antenna Abnormal update rate	Cab controller - primary Active Count : 126
SPN 1482,FMI 9	Source address of controlling device for transmission control Abnormal update rate	Cab controller - primary Active Count : 3

Brakes - system controller (2 DTCs)

DTC	Description	Status
SPN 639,FMI 2	J1939 network #1, primary vehicle network Data erratic, intermittent or incorrect	Brakes - system controller Active Count : 127
SPN 639,FMI 14	J1939 network #1, primary vehicle network Special instructions	Brakes - system controller Previously Count : 1

Engine #1 (13 DTCs)

DTC Description Status

AUTEL www.autel.com

MaxiSys CV

Page 1

//ID ODD /217 1157	T . T . 2007 27 27 27 27	D I ID
/HD OBD/SAE J1939	7 Test Time: 2025-06-04 11:40:50	Report ID: MAXIA20250604114050
SPN 1172,FMI 2	Engine turbocharger 1 compressor intake temperature Data erratic, intermittent or incorrect	Engine #1 Active Count : 1
SPN 191,FMI 9	Transmission 1 output shaft speed Abnormal update rate	Engine #1 Active Count : 1
SPN 84,FMI 9	Wheel-based vehicle speed Abnormal update rate	Engine #1 Active Count : 1
SPN 563,FMI 9	Anti-lock braking (ABS) active Abnormal update rate	Engine #1 Previously Count : 1
SPN 96,FMI 9	Fuel level 1 Abnormal update rate	Engine #1 Previously Count : 1
SPN 3597,FMI 2	ECU power output supply voltage #1 Data erratic, intermittent or incorrect	Engine #1 Emissions-related Count : 4
SPN 1172,FMI 2	Engine turbocharger 1 compressor intake temperature Data erratic, intermittent or incorrect	Engine #1 Emissions-related Count : 1
SPN 191,FMI 9	Transmission 1 output shaft speed Abnormal update rate	Engine #1 Emissions-related Count : 1
SPN 84,FMI 9	Wheel-based vehicle speed Abnormal update rate	Engine #1 Emissions-related Count : 1
SPN 3597,FMI 2	ECU power output supply voltage #1 Data erratic, intermittent or incorrect	Engine #1 Permanent Count : 4
SPN 1172,FMI 2	Engine turbocharger 1 compressor intake temperature Data erratic, intermittent or incorrect	Engine #1 Permanent Count : 1
SPN 191,FMI 9	Transmission 1 output shaft speed Abnormal update rate	Engine #1 Permanent Count : 1
SPN 84,FMI 9	Wheel-based vehicle speed Abnormal update rate	Engine #1 Permanent Count : 1

/HD OBD/SAE J1939/ Test Time: 2025-06-04 11:40:50 Report ID: MAXIA20250604114050

Technician Notes

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



www.autel.com MaxiSys CV Page 3