



Shop:
Tel:
Address:

Report ID: MAXIA20220609
Creation Date: 2022-06-09



HD OBD Vehicle Diagnostic Report

License Plate: 25184320-1

Manufacturer: HD OBD

Year:

Model: SAE J1939

Sub Model:

Engine:

Path: HD OBD>SAE J1939>DTC&FFD

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
SPN 652,FMI 11	Engine injector cylinder #02. Root cause not known	Engine #1 Active Count : 127
SPN 639,FMI 9	J1939 network #1, primary vehicle network Abnormal update rate	Engine #1 Active Count : 11