

2019 KENWORTH Vehicle Diagnostic Report

Vehicle Information

2019/KENWORTH/T680/
VIN: 1XKYDP9XXKJ229061

Odometer Reading: --
License Plate: 19KN042

Customer Information

Name: --
Tel: --

Device information

Scanner: MaxiSys MS909CV
Version: V1.00-1.40

Serial Number: V19GM4V01249
Repair Order Number:
V19GM4V0124920240809115905606

DTC (15)

DTC	Description	Status
P1105	Engine protection system - approaching engine shutdown	Inactive Count:16
P1106	Engine protection system - power derate active	Inactive Count:12
P1407	Crankcase air pressure - data valid but too low	Inactive Count:5
P1518	Aftertreatment system - engine torque derate active	Inactive Count:2
P1519	Aftertreatment system - Diesel Exhaust Fluid (DEF) level low	Inactive Count:14
P151A	Aftertreatment system - vehicle speed limitation active	Inactive Count:2
P151C	Aftertreatment system - Diesel Exhaust Fluid (DEF) level too low	Active Count:2
P151D	Aftertreatment system - Diesel Exhaust Fluid (DEF) level very low	Inactive Count:1
P151E	Aftertreatment system - Diesel Exhaust Fluid (DEF) tank empty	Inactive Count:2
P1560	Coolant level - data valid but too low (moderately severe)	Active Count:89
P2560	Coolant level - data valid but too low (most severe)	Inactive Count:29
P3797	Diesel Particulate Filter (DPF) - soot level (least severe)	Inactive Count:4
P3878	Hydrocarbon storage - level too high	Inactive Count:3
P3880	Hydrocarbon storage - drive off error	Inactive Count:12

P3927	Nitrogen Oxide (NOx) sensor after catalyst - data valid but too high	Inactive Count:0
-------	--	---------------------

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.