Report ID: MAXIA20250717115255 Test Time: 2025-07-17 11:52:55

Technician: --

# **HD OBD Vehicle Diagnostic Report**

### **Vehicle Information**

--/HD OBD/SAE J1939/

VIN: --

**Customer Information** 

Name: --

Tel: --

**Device information** 

Scanner: MaxiSys MS909CV

Version: V1.30

Serial Number: V19GM4V01376

Odometer Reading: 1258207miles

Repair Order Number:

License Plate: 07VV331

V19GM4V0137620250717115220154

### 🔁 System Scanned( 1 )

System Status/DTC **4** Brakes - system controller

## ▲ DTC (4)

### Brakes - system controller (4 DTCs)

DTC	Description	Status
SPN 639,FMI 2	J1939 network #1, primary vehicle network  Data erratic, intermittent or incorrect	Brakes - system controller Active Count : 127
SPN 1045, FMI 7	Brake light switch 1 Mechanical system not responding or out of adjustment	Brakes - system controller Active Count : 127
SPN 802,FMI 4	Relay diagonal 1 Voltage below normal, or shorted to low source	Brakes - system controller Previously Count : 1
SPN 639,FMI 12	J1939 network #1, primary vehicle network Bad intelligent device or component	Brakes - system controller Previously Count : 126

### **Technician Notes**

Customer name: Technician: \_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS909CV

Page 1