



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20250717115435
Test Time: 2025-07-17 11:54:35
Technician: --

HD OBD Vehicle Diagnostic Report

Vehicle Information

HD OBD/SAE J1939
VIN: --
Path: HD OBD>SAE J1939>Vehicle information

Odometer Reading: 1258207 miles
License Plate: 07VV331
Sub Model: --

Customer Information

Name: --
Tel: --

Device information

Scanner: MaxiSys MS909CV
Version: V1.30
Serial Number: V19GM4V01376

Vehicle information

Component identification	
Make	BNDWS
Model	EC60-pre
Serial version	T340622533
Software identification	
Software identification	BB40943

