Post Deman Walk Around	Dog house mount tabs inspected (edit part) (delete part) Duicktach Deck plate, pull all good ones in Deman
Deman Unit Open Set	Inventoried parts not full of garbage Cab cleaned out, parts being stored in cab organized
 □ VEHICLE WO DPEN □ SCRAP TRUCK PICKED □ SCRAPPED IN SCRAP APP □ EMAIL SENT □ EIF STARTED □ TAGS PRINTED □ DEMAN WO CLOSED 	Tool box/Battery Box cleaned out, not rusted out, no holes? (Edit part) (Delete Part) All Fluids drained All batteries/battery Cables pulled from Truck All parts marked w/ correct truck number and put on parts cart Wheels/Tires pulled
Complete pre-run checklist, Enter pre-run notes into EIF PRIOR to Running Engine.	Tires dismounted, wheels tagged, dirty ones should be washed Fuel and Hydro Tanks pulled
Review Deman Sheet to make sure all parts are pulled/dealt with before truck goes into the yard Condition of Doors acceptable (edit part) (delete part) Cage Bolts (pull all) Save Nice Seatbelt (END) (ASSEMBLY) (LH) (RH) (BOTH) Cracked Fairing Brackets? (Edit Part) (Delete Part) Bumper Still as Pictured/described? (edit part) (delete part) Hood (edit part) (delete part)	CRR Bolts/axle nuts put Back in Housing 5th Wheel inspected (Good) (Bad) Scrap Cleaned up and thrown away All parts that need washed moved to wash bay Clean floor as needed before next truck EIF completely filled out and signed. (this applies to all engines, used, core, unknown)
Mirrors (edit part) (delete part) Inner Fenders (edit part) (delete part) Inventory Fender mount brackets if Fenders are damaged Driveshafts Inspect, Measure, Tag, Picture Running Length 374 Yoke SPL250 Running Length 694 Yoke SPL250 Running Length 234 Yoke SPL250 Running Length 234 Yoke SPL250	POST DEMAN PICTURES NEED TO BE TAKEN OUTSIDE / NOT INSIDE I. FRONT LH CORNER OF VEHICLE 2. FRONT RH CORNER OF VEHICLE 3. RH SIDE OF VEHILE 4. BACK RH CORNER OF VEHICLE 5. BACK LH CORNER OF VEHICLE 6. LH SIDE OF VEHICLE 7. INSIDE DRIVER DOOR 8. INSIDE PASSENGER DOOR 9. PICTURE OF ALL PIPE/TUBES/MISC PARTS THAT ARE GOING BACK IN CAB
□ Axle shafts tag on shaft, install one nut finger tight SplinesDIAL(S) (T) SplinesDIAL(S) (T) SplinesDIAL(S) (T)	

☐ Axle housing physical condition okay(edit part) (delete part)

				Dismai	ntle	e Sheet	
011H368	2001	Internation	al 9200				2HSCEAHR11C091045
		Fluids Fuel Engine Coolant Power Steer Freon Brake Fluid Transmissio Differential(s	n s)] [] []	CRCIrNT	ismantle R/O hocked Wheels lesting on Jack Stands leaned Garbage out of Cab ispected parts for damage lark Frame Rail with Stock # ag Cores lost Deman Pictures	
oull Initials		Cnd	Status	Location	Tag		
	Hood Assy	В	Available	Deck		SHELL HOOD, CRACKED ON TOP PAN ALONG RH FENDER, PAINT CHIPPED	ON LH FRONT EDGE International
						9200 SBA WHITE SHELL 51	
	Radiator		Not Posted			ON OTHER PROBE	
	L Radiator Overflo	Made by the state of the state of the state of	Available		Ц	International 9200 CAB STEEL	
	Condensor		Not Posted		Ц		
	Cab	MAN BURLING BETAS	Not Posted		Ц		是这种 是一种的
	Cab Control Mod		Not Posted			LOOS VEG MANUAL NO NO	
	L Column	А	Available		Ц	International 9200 YES MANUAL NO NO	
	Seats		Not Posted	SEPTEMBER STATE OUT OF THE			
	Heater Motor		Not Posted			NO VERNICO DE PLA	VED
	Radio	A	Available		Ц	International 9200 NO YES NO CD PLA	TEX
	Fuel Tanks		Not Posted				10000000000000000000000000000000000000
	Air Tank		Not Posted	EST SERVICE A SPECIAL PROPERTY.	Ц		THE PARTY WAS THE PROPERTY OF THE PARTY OF T
	Wiper Motor		Not Posted				2000 25004767 220
	Engine	В	Available		Ц	Cummins ISM 180 Day Parts Only CPL	2608 35001767 330
	Fan		Not Posted		Щ	(中国的中华的中国中国中国的中国的中国的中国的中国的中国的中国的中国的中国的中国的中国的中国	
	Starter		Not Posted		Щ		
	Alternator		Not Posted		Ц		
	Flywheel		Not Posted				BELLEVOT DESERVED SER BESKUR LEGEN AV
	Steering Pump		Not Posted				
	A/C Compresso					Fulley EDOE142100 VEDIEV VEDIEV V	EDIEV VEDIEV
	Transmission		Available Available	W	Ц	Fuller FROF14210C VERIFY VERIFY V Meritor FF981 12000 AIR DRUM 32 10	中國 5.1.716 法师 医医院学生医院院 经产品的经验的
	Fr Axle			Α ()		Wellol FF981 12000 AIR DROW 32 10	BOLT PILOT
	Steering Gear	^	Not Posted Available	CP	Щ	International 9200 4.00 5 29.00 29	
	Fr Leaf Spring(1 Rr Axle(s)			Villaganisa a	\square		AID Voisi
	Brake Control M	AND THE RESIDENCE AND ADDRESS OF THE PARTY O	Available Not Posted	48.044.603030		Meritor RD20145 AIR DRUM PILOT IH	AIT Vally
	Power Divider		Available	(0		Meritor RD20145 4,10 41 NO 3226-U-1:	205 W. E. L. D. W. C. L. D. C. L. C.
	Carrier		SECOND SECURITION OF REAL PROPERTY.		H	Meritor RR20145 4.11 41 NO 3220-L-18	
	Axle Shafts(2)	Α	Available	UP.		1216 SHORT H -RR RH-FR Meritor 3	
126						THE RESERVE TO BE A STREET THE PARTY OF THE	

22.5

22.5

Pilot 22.5 ALUM Classic 2.5" Round Hole STEER 10 8.25

International 9200 ALUMINUM ASSEMBLY COMPLETE

Notes:

Dismantler Notes: ,

Rr Leaf Spring

Fifth Wheel

Equipment

Wheels(1)

Front Tires

Rear Tires

Not Posted

Not Posted

Not Posted

Not Posted

Not Posted

Available

A Available

						Page 2 of 4
	R Fender	A	Available			DOES NOT INCLUDE BRACKET, SOME MINOR PAINT RUBBING ON THE EDGE International 9200 WHITE EXTENSION FIBERGLASS
	Ship On: Counter Sale (None)					
CD	L Fender, Inner	Α	Available	LWV		MOUNTS TO HOOD International 9200
	R Fender, Innet	A	Available	Lur	H	MOUNTS TO HOOD International 9200
	L Headlamp Assembly	Α	Available	LW,		W/O BEZEL, TURN SIGNAL INCLUDED International 9200 SINGLE SEALED
ŎE	R Headlamp Assembly	A	Available	Lur		W/O BEZEL, TURN SIGNAL INCLUDED International 9200 SINGLE SEALED
	R Hood Mirror	Α	Available	Lw		HOOD MIRROR International 9200 STAINLESS STEEL NO NO
ÖL	Hood Hinge	eAs.	Available	Luv	Ö	BOTH SIDES W/ CROSSBAR AND LOWER HINGE International 9200 VERIFY
	Cab Assembly	-	Available			International 9200 AIR CUMMINS ISM FOR PARTS DAY CAB
	L Air Dryer	A	Available	Lur		Meritor R955082
	L Seat (Air Ride Seat)	С	Available	DWV		DRIVER SIDE, HAS LARGE TEAR ON THE BACK REST. International 9200 HIGH HIGH CLOTH BROWN
	R Seat (Air Ride Seat)	A	Available			PASSENGER SIDE International 9200 HIGH HIGH CLOTH BROWN
	R Door Interior Panel	Α	Available		\Box	International 9200 BROWN YES
	Dash Assembly	1	Available	Carling to 45		International 9200 CUMMINS ISM AIR MANUAL FOR PARTS
	Dash Panel	Α	Available			LIGHTS, PARKING LIGHT, PANEL, WIPER CONTROLS, DIAG, CRUISE SET, CRUISE ON/OFF, POWER MIRROR RIGHT, RIGHT WINDOW. International 9200 GAUGE AND SWITCH PANEL - CUMMUNS ISM 9
	L Dash Panel	Α	Available			WATER TEMP, OIL PSI, VOLTS International 9200. GAUGE AND SWITCH PANEL 3 CUMMINS ISM 0
	Dash Panel	Α	Available			CENTER CUPHOLDER / CONSOLE, NEEDS CLEANING International 9200
	Dash Panel	A	Avail a ble			CUP HOLDER - CUMMUNS ISM 0 AIR 1 PRESSURE, AIR 2 PRESSURE, FUEL International 9200 GAUGE AND SWITCH PANEL 3 CUMMINS ISM 0
	L Instrument Cluster	Α	Available	PA		TACH & SPEEDO International 9200 2 CUMMINS ISM VERIFY
DIV	Drive Shaft, Rear	A	Available	1	ĭ	All Other ANY CARRIER BEARING SHAFT VERIFY VERIFY
9	Drive Shaft, Rear	Α	Available	11.11		All Other ANY SLIP SHAFT VERIFY VERIFY
	Drive Shaft, Rear	Α	Available	LWV		All Other ANY INTERAXLE SHAFT VERIFY VERIFY
	Axle Housing (Rear)	A	Available	Non-Blackholm Volcalista		Meritor RR20145 AIR DRUM PILOT IH AIR Verify
in the second of	Suspension	Α	Available		Ī	SUSPENSION ONLY, DOES NOT INCLUDE HOUSING International IH AIR IROS 40000 53
	Frame	Α	Available	1		Misc Manufacturer ANY 10 - 10.00 1/4 - 0.2500 3 1/2 - 3.50 no
OL	L Steering Reservoir/Cooler	A	Available	LW		International 9200 FRAME STEEL
	Battery Box	В		100000000000000000000000000000000000000		DOES NOT INCLUDE COVER OR STEP International 9200 47.00 25.0 4 ALUMINUM
	R Windshield Washer Reserve		DAMESTING LISTAN			International 9200 CAB
	Heater & AC Temperature Co					3 KNOBS AND 1 BUTTON International 9200
	Cooling Assembly. (Rad., Co	A	Available	W		COMPLETE COOL PACK W/ RADIATOR, CHARGE AIR COOLER, AND A/C CONDENSER; DOES NOT INCLUDE OVERFLOW BOTTLE OR SHROUD International 9200 VERIFY VERIFY VERIFY CUMMINS ISM

SPECIAL INVENTORY / DISMANTLE INSTRUCTIONS This unit has a hood HINGE in inventory. BE SURE IT DOES NOT GET LEFT ON HOOD Hood Hinge AFTER DEMAN. IF IT IS DECIDED TO LEAVE IT WITH THE HOOD, THE HOOD HINGE PART RECORD NEEDS TO BE REMOVED FROM INVENTORY. This unit has inventoried headlamps! Don't throw the hood away with the headlamps in it, or Headlamp Assembly shelf it with the headlamps in it. Remove them and send them through the warehouse process for more pictures, and shelving. Inventoried headlamps should not make it to the yard. This unit has an inventoried GRILLE we don't want the grille to go to the shelf with the hood Grille or get scrapped, pull the grille and send it through the warehouse process. This unit has an inventoried HOOD MIRRORS! We don't want the mirrors to go to the Hood Mirror shelf with the hood or get scrapped, pull the mirror(s) and send through the warehouse process. INNER FENDERS ARE INVENTORIED! INSPECT INNER FENDERS! ALERT LEAD OF Fender, Inner DAMAGE!