



Shop: --
Tel: --
Email:
Address: --

Report ID: MAXIA20250122125243
Test Time: 2025-01-22 12:52:43
Technician: --

HD OBD Vehicle Diagnostic Report

Vehicle Information

HD OBD/SAE J1939
VIN: --
Path: Autoscan general > Live data > Instrument cluster #1 > ALL >

Odometer Reading: --
License Plate: --
Sub Model: --

Customer Information

Name: --
Tel: --

Device information

Scanner: MaxiSys CV
Version: V6.80
Serial Number: V59SP5V01172

Instrument cluster #1 -- ALL

NO.	Name	Value	Unit
1	Illumination brightness percent	0.0	%
2	Operator desired display mode command 1	Not available	bit
3	Operator desired display mode command 2	Not available	bit
4	Total vehicle distance (high resolution)	989308885	m
5	Trip distance (high resolution)	0	m
6	Barometric pressure	0.00	psi
7	Ambient air temperature	87.18	°F
8	Illumination brightness percent	0.0	%
9	Switch indication illumination brightness percent	9.2	
10	Operator desired display mode command 1	Mode 1	
11	Operator desired display mode command 2	Mode 1	