Post Deman Walk Around	Dog house mount tabs inspected (edit part) (delete part) Ouicktach Deck plate, pull all good ones in Deman	
Deman Unit MIHIST .	Inventoried parts not full of garboge	
Scrap Unit 19EKON-74852	Cab cleaned out, parts being stored in cab organized	
VEHICLE WO OPEN	Tool box/Battery Box cleaned out, not rusted out, no holes? (Expert) (Delete Part)	
SCRAP TRUCK PICKED SCRAPPED IN SCRAP APP	All Fluids drained	
EMAIL SENT	All batteries/battery Cables pulled from Truck	
TAGS PRINTED	All parts marked w correct truck number and put on parts ca	
DEMAN WO CLOSED		
	Wheels/Tires pulled	
☑ Complete pre-run checklist, Enter pre-run notes	Tires dismounted, wheels tagged, dirty ones should be washe	
into EIF PRIOR to Running Engine.	☐ Fuel and Hydro Tanks pulled	
Review Deman Sheet to make sure all parts are	CRR Bolts/exle nuts put Back in Housing	
pulled/dealt with before truck goes into the yard	5th Wheel inspected (Good) (Bad)	
Condition of Doors acceptable (edit part) (delete part) Druck Louse	Scrap Cleaned up and thrown away	
Cage Bolts (pull all)	All parts that need washed moved to wash bay	
Save Nice Seatbelt (END) (ASSEMBLY) (LH) (RH) (BOTH)	Clean floor as needed before next truck	
Cracked Fairing Brackets? (Edit Part) (Delete Part)		
Bumper Still as Pictured/described?(edit part) (delete part)	EIF completely filled out and signed. (this applies to all engines, used, cor	
Hood (edit part) (delete part)	unknown)	
Dash (edit part) (delete part)	POST DEMAN PICTURES NEED TO BE TAKEN OUTSIDE / NOT INSIDE	
Mirrors (edit part) (delete part)	I. FRONT LH CORNER OF VEHICLE 2. FRONT RH CORNER OF VEHICLE	
	3. RH SIDE OF VEHILE	
Inner Fenders (edit part) (delete part) (4200	4. BACK RH CORNER OF VEHICLE 5. BACK LH CORNER OF VEHICLE	
Inventory Fender mount brackets if Fenders are damaged	6. LH SIDE DF VEHICLE 7. INSIDE DRIVER DOOR	
\ □ Driveshafts Inspect, Measure, Tag, Picture	B. INSIDE PASSENGER DOOR 9. PICTURE OF ALL PIPE/TUBES/MISC PARTS THAT ARE GOING BACK IN CA	
SINRunning LengthYake	G. FIGURE OF ALL JIE & TOUCH AND THAT ARE BOING GARAGE OF SHIP	
Running LengthYoke Running Length Yoke		
Running Length Yoke		
Axle shafts tag on shaft, install one nut finger tight Splines DIA L (S) (T)	7.00	
Splines DIA L (S) (T)		
Splines DIA L(S) (T) Splines DIA L (S) (T)		

☐ Axle housing physical condition okay(edit part) (delete part)

Dismantle Sheet

AA185JHA31822 1979 International S1800 79IH151 Fluids ☐ Dismantle R/O ☐ Fuel □ Chocked Wheels ☐ Engine ☐ Resting on Jack Stands ☐ Coolant □ Cleaned Garbage out of Cab Power Steering ☐ Inspected parts for damage Freon ☐ Mark Frame Rail with Stock # Brake Fluid Tag Cores Transmission □ Post Deman Pictures Differential(s) Fluids Drained by oull initials Cnd Status Location Tag COMPLETE HOOD, CRACKED ALONG LH FRONT EDGE, AND RH B Available LOWER END COVERED BY MOULD SPOTS THROUGHOUT International \$1800 SBA WHITE COMPLETE 42 International S1800 INTERNATIONAL DT466B 31 00 26 00 2 50 Available Radiator SURAFCE RUST International \$1800 CAB STEEL Radiator Overflow Bottle A Available Not Posted Condensor Not Posted Cab Cab Control Module Not Posted Not Posted Column Not Posted Seats Not Posted Heater Motor Not Posted 50 GALLON STEEL TANK ONLY, 4" RTF, HAS SURFACE RUST A Available Fuel Tanks International S1800 50 36 25 15 Not Posted Air Tank Not Posted Wiper Motor International DT466B As-Is No Warranty VERIFY VERIFY -Engine C180 Available

Not Posted Fan Starter Not Posted Not Posted Alternator Not Posted Flywheel Not Posted Steering Pump Not Posted A/C Compressor Spicer (Ttc) CM5252A VERIFY VERIFY VERIFY VERIFY Transmission A Available International ALL 10800 HYDRAULIC DRUM 35 DAYTON Available Fr Axle Not Posted Steering Gear Not Posted Fr Leaf Spring Not Posted Rr Axle(s) **Brake Control Module** Not Posted Power Divider Not Posted Eaton 17220 - VERIFY NO 106411 Available Carner Eaton ALL OTHER VERIFY VERIFY VERIF Axle Shafts(1) Available International S1800 3 11 25 25 Available Rr Leaf Spring(1) Fifth Wheel Not Posted Not Posted Equipment Not Posted Wheels Not Posted 22.5 Front Tires Rear Tires Not Posted CRACKS BY EACH SIDE OF TOW HOOK, SCRATCH & SURFACE Bumper Assembly, Front Available RUST MULTIPLE WELDS ALONG BOTTOM EDGE. International \$1800

PIECE SFA STEEL NO

Notes:

79IH151	1979 Internation	onal S1800	AA185JHA31822 Page 2 of 3
	L Fender	B Available	DOES NOT INCLUDE BRACKET, RUSTING ON BOTH SIDES International S1800 WHITE EXTENSION STEEL
	R Fender	B Available	DOES NOT INCLUDE BRACKET, RUSTING ON BOTTOM International S1800 WHITE EXTENSION STEEL
	Door Assembly, Front	B Available	COMPLETE, DOES NOT INCLUDE MIRROR, RUSTED ALONG EDGES, HAS MOULD AND PAINT SCRAPES SPOTS MISSING LOWER INNER COVER International S1800 WHITE NO NO COMPLETE DOES NOT LINCLUDE MIRROR
	Door Assembly, Front	A Available	COMPLETE, DOES NOT INCLUDE MIRROR, RUSTED ALONG BOTTOM EDGE, HAS MOULD SPOTS. International S1800 WHITE NO NO COMPLETE DOES NOT INCLUDE MIRROR
	Cab Assembly	A Available	EXTENSIVE RUST ON BODY EDGES, MOULD SPOTS ALL OVER BODY International S1800 HYDRAULIC INTERNATIONAL DT466B FOR PARTS DAYCAB
	Instrument Cluster	A Available	TACH, SPEEDO, OIL TEMP, PSI, VOLTS, FUEL International S1800 6
	Air Transfer Tube	A Available	COWL TO AIR CLEANER International S1800 INTERNATIONAL DT466B
	Air Cleaner Hydraulic Pump	A Available LWV	International S1800 12 STEEL DONALDSON INTERNAL WILLIAMS BI-DIRECTIONAL HYDRAULIC PUMP W/VALVE All Other ALL
	Axle Housing (Rear)	A Available	Pump Remote Mount 1 1/4 Keyed (SAE C) Eaton 17220 HYDRAULIC DRUM DAYTON IH SPRING 72
	Suspension	A Available	SUSPENSION ONLY, DOES NOT INCLUDE HOUSINGS International IH
	Frame	A Available	SPRING IH SPRING 19000 S/A Misc Manufacturer ANY 10 - 10.00 1/4 - 0.2500 3 no
	Steering Reservoir/Cooler	A Available LUJ	International S1800 ENGINE STEEL SINGLE CYLINDER HOIST, DOES NOT INCLUDE RESERVOIR All Other
	Assembly	International DT466B - If 400LV/400HV/600/700/80	this engine has a U-MODEL EATON PUMP 00 like sku 24446323 inventory it as good used to the stock core, use sku 24446323. Pull it and and shelf it.
i and			Example SKU: 24446323
Engine	Assembly		this unit has hydraulic brakes, pull the hydraulic pump;mark a end through the warehouse
		, Pa	
	*		Example SKU: 24190900
. 1			
Transmi	ssion	Spicer (Ttc) - PULL THE	TRANSMISSION SHIFT LEVER AND KNOB AND INVENTORY IT
7			

2/7 Please ship to customer Ship On: Ship to Customer

Notes:

